INSPECTION REPORT

PERMIT NUMBER:	BP-14-00280	OWNER'S NAME:	SORENSON
DATE:	10/29/2014	TYPE:	Gas piping
TIME STARTED:	12:48 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-19-31010-0021		
1. gas at	20#/15 min ok		
2. gas fire	eplace rough in ok		
INSTRUCTIONS: ga	s ok		
NEXT INSPECTION:	Final		
RE-INSPECTION FEE I	DUE? NO YES	3	\$
IF REQU	UIRED, RE-INSPECTION FEES MUST BE	E PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ◆ 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506 			