



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-14-00315 OWNER'S NAME: QUITADAMO
DATE: 1/15/2015 TYPE: Insulation
TIME STARTED: 11:14 AM INSPECTOR: Amber Green
MAP NUMBER: 18-17-36051-0016

	1. Insulate range vent.
	2. Complete fireplace vent pipe.
	3. Insulation OK

INSTRUCTIONS: Complete #1 and #2, call for re-inspection. Ok to cover walls only.

NEXT INSPECTION: Fireplace Vent Piping/Range Vent

RE-INSPECTION FEE DUE? ☒ NO ☐ YES \$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

amber.green @co.kittitas.wa.us

• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506