INSPECTION REPORT

PERMIT NUMBER:

BP-14-00401

OWNER'S NAME: SCHEMM

DATE:		1/9/2015	TYPE:	Gas piping	
TIME STARTED:		2:12 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		20-14-24050-0206			
	1. gas at	15#-ok			
	i. gas at	10#-01			
INSTRUCTIONS:					
NEXT INSPECTION: re-shear/frame/mech					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	jessica.contratto @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ◆ 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506 					