



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-14-00401

OWNER'S NAME: SCHEMM

DATE: 11/12/2015

TYPE: Final

TIME STARTED: 4:22 PM

INSPECTOR: Jessica Contratto

MAP NUMBER: 20-14-24050-0206

	1. Fireplaces not functioning
	2. Blower door test ok- 4.57
	3. Photos provided of can light fire enclosures in garage
	4. CO detector needed outside bonus room

INSTRUCTIONS: complete above, call for re-inspection

NEXT INSPECTION: re-inspect

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506