INSPECTION REPORT

PERMIT NUMBER:		BP-14-00434	OWNER'S NAME:	BURNSTEAD	
DATE:		1/12/2015	TYPE:	Frame-Plumb-Mech	
TIME STARTED:		11:50 AM	INSPECTOR:	Amber Green	
MAP NUMBER:		20-14-13050-0024			
1. C	1. Complete knee brace attachments per A7 and A8.				
2. C	2. Complete mechanical work.				
3. Place plumbing on test.					
4. Anchor bolts at interior bearing walls. 48" o.c. per shear schedule.					
5. Gasline (15#/15mins) - OK					
INSTRUCTIONS: Complete Above, OK TO INSULATE.					
NEXT INSPECTION: INSULATION/CORRECTIONS					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	amber.green @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506					