INSPECTION REPORT

OWNER'S NAME: SINNETT

PERMIT NUMBER: BP-14-00449

DATE:	9/3/2015	TYPE:	Gas piping
TIME STARTED:	10:13 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-14050-0925		
dryer vent must terminate to outside of building with backdraft damper			
2. gas piping cannot penetrate foundaton below grade			
INSTRUCTIONS: address above corrections			
NEXT INSPECTION: re-inspection			
RE-INSPECTION FEE DUE? VES \$ IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			