INSPECTION REPORT

PERMIT NUMBER: BP-14-00467 OWNER'S NAME: MAKI

DATE:		10/2/201	5	TYPE		Footings	
TIME STARTED:		11:53 AN	M	INSP	INSPECTOR:	Jessica Contratto	
MAP	NUMBER:	1-14-020)52-0001				
	1. setbacks ok						
INSTR	CUCTIONS: C	k to pour					
NEXT	INSPECTION:	walls					
RE-IN	SPECTION FEI	DUE?	✓ NO	YES		\$	
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION							
	Q	UESTIONS? PLE	ASE CONTACT T	HE INSPECTOR	AT THE FOLL	OWING E-MAIL ADDRESS:	
	iessica.contratto @co.kittitas.wa.us						
						quest.asp or 509-962-7694 •	
	4	II N. KUDY STRE	et, Suite 2, Eller	isburg, WA 989	zo • iviain C	Office Line: 509-962-7506	