INSPECTION REPORT

TYPE:

BP-14-00608

12/23/2014

PERMIT NUMBER:

DATE:

OWNER'S NAME: LAHAIE

Exterior shear

TIME STARTED:	10:52 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-18-07058-0003		
1. add	straps at front		
INSTRUCTIONS:	shear ok. Ok to cover		
NEXT INSPECTIO	N: framing		
RE-INSPECTION I	FEE DUE? NO YE	S	\$
IF F	REQUIRED, RE-INSPECTION FEES MUST B	E PAID PRIOR TO S	CHEDULING A RE-INSPECTION
	QUESTIONS? PLEASE CONTACT THE INSP	PECTOR AT THE FOL	LOWING E-MAIL ADDRESS:
	jess	sica.contratto @	co.kittitas.wa.us
• INS	PECTION REQUEST LINE: www.co.kit		
	411 N. Ruby Street, Suite 2, Ellensburg,	WA 98926 • Main	Office Line: 509-962-7506