INSPECTION REPORT

PERMIT NUMBER: BP-14-00629 OWNER'S NAME: BURNETT

DATE: TIME STARTED: MAP NUMBER:		5/15/2015 10:51 AM	TYPE:	Footings Jessica Contratto	
			INSPECTOR:		
		20-15-26063-0014			
	1. Footings	ings and setbacks ok			
INSTRUCTIONS: ok to pour. See interior strip and piers at later inspection					
NEVT	INSPECTION:				
walls					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	iessica.contratto @co.kittitas.wa.us				
		CTION REQUEST LINE: www.co. 11 N. Ruby Street, Suite 2, Ellensbu			