INSPECTION REPORT

PERMIT NUMBER:	BP-14-00649	OWNER'S NAME:	TERRELL
DATE:	1/20/2015	TYPE:	Insulation
TIME STARTED:	12:31 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	16-20-22000-0013		
1. attach	tub flanges		
INSTRUCTIONS: ins	sulation ok. ok to cover		
NEXT INSPECTION:	final		
RE-INSPECTION FEE I	DUE? NO YES	.	\$
	UIRED, RE-INSPECTION FEES MUST BE		
QUI	ESTIONS? PLEASE CONTACT THE INSP jess	ECTOR AT THE FOLLOW ica.contratto @co.ki	
	TION REQUEST LINE: www.co.kitt I. N. Ruby Street, Suite 2, Ellensburg, N		