INSPECTION REPORT

PERMIT NUMBER:	BP-14-00675	OWNER'S NAME:	MOINE
DATE:	12/5/2014	TYPE:	Slab insulation
TIME STARTED:	12:09 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-19010-0008		
1. slab in	sulation ok		
2. no plai	ns/permit on site		
INSTRUCTIONS: OK	to pour		
NEXT INSPECTION:	shearwalls		
RE-INSPECTION FEE	DUE? NO YES	;	\$
IF REQ	UIRED, RE-INSPECTION FEES MUST BE	E PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
, INCOPEO		ica.contratto @co.ki	
	TION REQUEST LINE: <u>www.co.kitt</u> 1 N. Ruby Street, Suite 2, Ellensburg, N		