INSPECTION REPORT

TYPE:

PERMIT NUMBER:

DATE:

BP-14-00675

4/7/2015

OWNER'S NAME:

MOINE

Framing

TIME STARTED:		1:27 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:		20-14-19010-0008		
1. Exterior Shear Ok				
	2. Ok to cover Exterior			
INSTRUCTIONS: Ok to cover Exterior/Framing cannot be inspected until electrical is installed				
NEXT INSPECTION: Framing				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
justin.bennett @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 				