## **INSPECTION REPORT**

OWNER'S NAME: MOINE

TYPE:

Final

PERMIT NUMBER: BP-14-00675

8/5/2015

DATE:

TIME STARTED:		1:22 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		20-14-19010-0008			
	water heater requires seismic straps				
	2. WUIC final needs completed				
INSTRUCTIONS:					
NEXT INSPECTION: Re-final/WUIC					
RE-IN:	SPECTION FEE	DUE? NO ON NO	YES T BE PAID PRIOR TO SCI	\$ HEDULING A RE-INSPECTION	
	QL	JESTIONS? PLEASE CONTACT THE IN	SPECTOR AT THE FOLLO	DWING E-MAIL ADDRESS:	
	iessica.contratto @co.kittitas.wa.us				
	• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506				