## **INSPECTION REPORT**

PERMIT NUMBER: BP-14-00682 OWNER'S NAME: MCARTHUR

DATE:	5/14/2015	TYPE:	Exterior shear
TIME STARTED:	1:37 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-14050-0920		
1. 4 MSTA	48 straps missing at back	of house	
INSTRUCTIONS: j	nstall straps, ok to cover ex	terior	
NEXT INSPECTION:	plumb/mech		
RE-INSPECTION FE	E DUE? NO	YES	\$
IF RE	QUIRED, RE-INSPECTION FEES N	IUST BE PAID PRIOR TO SCI	HEDULING A RE-INSPECTION
Q	UESTIONS? PLEASE CONTACT TH	IE INSPECTOR AT THE FOLL	OWING E-MAIL ADDRESS:
		iessica.contratto @co	o.kittitas.wa.us
	CTION REQUEST LINE: www. 11 N. Ruby Street, Suite 2, Ellen		quest.asp or 509-962-7694 • Office Line: 509-962-7506