## **INSPECTION REPORT**

PERMIT NUMBER: BP-14-00682 OWNER'S NAME: MCARTHUR

DATE:	6/25/2015	TYPE:	Gas piping
TIME STARTED:	11:48 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-14-14050-0920		
1. Gas @ 25#/15 mins - Ok			
2. Fireplace rough-in - Ok			
3. Mechanical Ok			
INSTRUCTIONS:			
NEXT INSPECTION: Plumbing			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iustin_bennett @co.kittitas.wa.us			
<ul> <li>INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926</li> <li>Main Office Line: 509-962-7506</li> </ul>			