INSPECTION REPORT

PERMIT NUMBER:

BP-14-00682

OWNER'S NAME:

MCARTHUR

DATE:		7/24/2015	TYPE:	Radiant heat
TIME STARTED:		1:56 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:		20-14-14050-092	20	
1	1. upstairs hydronics at 100#-ok			
INSTRUCTIONS: ok to cover				
NEXT INSPECTION: insulation/truss bracing in garage				
RE-INSP	PECTION FEE	DUE? NO [YES UST BE PAID PRIOR TO SCI	\$ HEDULING A RE-INSPECTION
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: jessica.contratto @co.kittitas.wa.us				
		CTION REQUEST LINE: www.q L1 N. Ruby Street, Suite 2, Ellens		quest.asp or 509-962-7694 • Office Line: 509-962-7506