INSPECTION REPORT

PERMIT NUMBER:	BP-14-00682	OWNER'S NAME:	MACARTHUR
DATE:	1/26/2016	TYPE:	Final
TIME STARTED:	9:59 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-14-14050-0920		
 Complete exterior siding @ garage (3rd Bay) Provide L&I Final (Verify next inspection) Blower Door Ok (2.44) Maintain fire seperation @ garage wall Range Ok Range hood Ok Fireplace final Ok Complete electrical in Master Closet Basement fireplace not operable Maintain fire separation in mechanical room Plumbing Ok Mechanical Ok Complete railing @ back deck off laudry Fire final Ok Water and Access Ok by Suncadia 			
INSTRUCTIONS: Complete corrections above/Re-Inspection			
NEXT INSPECTION:			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS: <u>iustin.bennett</u> @co.kittitas.wa.us			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506