## **INSPECTION REPORT**

TYPE:

**PERMIT NUMBER:** 

DATE:

BP-14-00707

12/8/2014

OWNER'S NAME: GROENKE

Exterior shear

TIME STARTED:	3:33 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-19-32063-0001		
1. exte	rior and interior shear ok		
INSTRUCTIONS: ok to cover			
NEXT INSPECTION	V: framing/final		
RE-INSPECTION F	EE DUE? NO YE	S	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
<ul> <li>INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926</li> <li>Main Office Line: 509-962-7506</li> </ul>			