INSPECTION REPORT

PERIVITI NUIVIBER:	BP-14-00742	OWNER'S NAIVIE:	ROUSE
DATE:	12/4/2014	TYPE:	Mechanical
TIME STARTED:	10:22 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-20-07057-0002		
1. stove i	nstall ok		
2. clearai	nces, venting, fresh air o	k	
INSTRUCTIONS: fin	al ok		
NEXT INSPECTION:	N/A		
RE-INSPECTION FEE	DUE? NO YES	6	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: jessica.contratto @co.kittitas.wa.us			
	TION REQUEST LINE: www.co.kitt 1 N. Ruby Street, Suite 2, Ellensburg, V		