INSPECTION REPORT

PERMIT NUMBER:	BP-14-00765	OWNER'S NAME:	HALL
DATE:	1/15/2015	TYPE:	Floor framing
TIME STARTED:	12:29 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-20058-0135		
1. floor fr	aming ok		
2. comple	ete LSL blocking		
INSTRUCTIONS: ok to cover			
NEXT INSPECTION:	exterior shear		
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
		ica.contratto @co.ki	
	TION REQUEST LINE: www.co.kitt 1 N Ruby Street Suite 2 Fllensburg V		