



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-14-00765

OWNER'S NAME: HALL

DATE: 5/12/2015

TYPE: Mechanical and plumbir

TIME STARTED: 11:58 AM

INSPECTOR: Jessica Contratto

MAP NUMBER: 20-15-20058-0135

| | |
|--|---|
| | 1. maintain clearance to combustibles on master bed fireplace chimney |
| | 2. 3" clearance on top of main fireplace unit |
| | 3. DWV on stack-ok |
| | 4. H2O is live |
| | 5. draft stop at supply duct penetration to attic upstairs |
| | 6. venting ok |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

INSTRUCTIONS: see range vent at final. Complete above, see at framing

NEXT INSPECTION: framing

RE-INSPECTION FEE DUE? NO YES \$ _____
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____ jessica.contratto@co.kittitas.wa.us

• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506