## **INSPECTION REPORT**

TYPE:

**PERMIT NUMBER:** 

DATE:

BP-14-00779

2/19/2015

OWNER'S NAME:

**WHELPLEY** 

Gas piping

TIME STARTED:	1:59 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-13-11050-0058		
1. Framing Ok			
Provide correct stamped truss sheets			
INSTRUCTIONS: Ok to insulate			
NEXT INSPECTION: Insulation/Trusses			
RE-INSPECTION FE	E DUE? NO YES	5	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
justin.bennett @co.kittitas.wa.us			
<ul> <li>INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 ◆</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506</li> </ul>			
FIT IV. Naby Street, Saite 2, Elicisburg, WA 30320 9 Wall Office Elic. 303 302 7300			