## **INSPECTION REPORT**

PERMIT NUMBER:	BP-14-00779	OWNER'S NAME:	WHELPLEY
DATE:	3/4/2015	TYPE:	Final
TIME STARTED:	1:28 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-13-11050-0058		
1. Attic in	sulation Ok		
2. Final C	)k		
INSTRUCTIONS: Fir	nal Ok		
NEXT INSPECTION:	N/A		
RE-INSPECTION FEE	DUE? NO YES		\$
	UIRED, RE-INSPECTION FEES MUST BE		
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
justin.bennett @co.kittitas.wa.us			
<ul> <li>INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926</li> <li>Main Office Line: 509-962-7506</li> </ul>			