INSPECTION REPORT

OWNER'S NAME: CHRYSANTHAKOPOU

PERMIT NUMBER: BP-14-00784

DATE:		8/31/2015	TYPE:	Re-inspection	
TIME STARTED:		1:26 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		20-17-31051-0001			
	1. gas at 22	2#-ok			
	2. blocking at 48" per 5/SD1				
	3. insulatio	. insulation ok			
INSTRUCTIONS: add blocking or obtain engineer approva for omitttance. Do not cover until fixed or					
addressed. Re-inspect if installed. Email approval if omitted for ok to cover					
NEXT INSPECTION: re-inspect or final					
RE-INSPECTION FEE DUE? V NO YES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	iessica.contratto @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 					
	4.	zz iv. Naby Jareet, Jane 2, Enerisburg	5) **/(50520 ° Walli O	11100 Line. 303 302 7300	