INSPECTION REPORT

PERMIT NUMBER:	BP-14-00793	OWNER'S NAME:	THE PASS LLC
DATE:	12/1/2014	TYPE:	Mechanical
TIME STARTED:	11:24 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	22-11-09051-0057		
1. mecha	nical ok		
2. complete attacment of equipment in mezzanine			
3. possibly check refrigerant charge on compressor in mezzanine area. iced up lines			
INSTRUCTIONS: provide airflow balance worksheets at final for RTU			
NEXT INSPECTION: final			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			