## **INSPECTION REPORT**

PERMIT NUMBER:	BP-14-00818	OWNER'S NAME:	CAHILL
DATE:	4/29/2015	TYPE:	Floor framing
TIME STARTED:	9:59 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-20058-0094		
1. floor fra	aming ok		
2. galvanized nails on all treated wood			
INSTRUCTIONS: OK	to cover		
NEXT INSPECTION: 5	shearwalls		
RE-INSPECTION FEE I	OUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
<ul> <li>INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 ◆</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506</li> </ul>			