## **INSPECTION REPORT**

PERMIT NUMBER:	BP-14-00818	OWNER'S NAME:	CAHILL
DATE:	6/18/2015	TYPE:	Mechanical and plumbir
TIME STARTED:	10:38 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-15-20058-0094		
1. Corrections Ok			
2. Gas @ 16#/15 mins - Ok			
3. Supply @ 85#/15 mins - Ok			
4. Waste on Stack - Ok			
5. Mechanical Ok			
6. Plumbing rough-in Ok			
INSTRUCTIONS:			
NEXT INSPECTION: Framing			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iustin_bennett @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			