## **INSPECTION REPORT**

PERMIT NUMBER: BP-14-00818 OWNER'S NAME: CAHILL

DATE:		6/25/2015	TYPE:	Insulation	
TIME STARTED:		12:16 PM	INSPECTOR:	Justin Bennett	
MAP NUMBER:		20-15-20058-0094			
	1. Correction	s not complete			
	2. Provide vapor barrier @ exterior wall in upstairs bathroom				
INSTRUCTIONS: Complete previous corrections/insulation corrections/Re-inspection					
NEXT INSPECTION: Re-Inspection					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
iustin_bennett @co.kittitas.wa.us					
<ul> <li>INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 ◆</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506</li> </ul>					