



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

## INSPECTION REPORT

PERMIT NUMBER: BP-14-00818 OWNER'S NAME: CAHILL  
DATE: 9/30/2015 TYPE: Final  
TIME STARTED: 12:22 PM INSPECTOR: Jessica Contratto  
MAP NUMBER: 20-15-20058-0094

	1. Seal all holes in furnace alcove wall. Seal sheetrock to duct at ceiling
	2. Door from garage to residence to be self closing
	3. Grippable handrail with end returns required at stairs
	4. Sewer approval letter from Suncadia needed
	5. Blower door test results not on site
	6. Complete dishwasher drain installation with air gap
	7. Whole house ventilation sysem ok
	8. Furnace and on demand water heater satisfy energy credits
	9. Sprinkler head at master bed not trimmed out
	10. CO detector needed outside upstairs bedrooms. Plug in type acceptable or provide liter ature for effective range of CO detector at den
	11. Gas heater in garage not on plans. Additional permit fees apply

INSTRUCTIONS: complete above, call for re-inspect

NEXT INSPECTION: re-inspect

RE-INSPECTION FEE DUE?



NO



YES

\$ \_\_\_\_\_

**IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION**

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

\_\_\_\_\_ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

• INSPECTION REQUEST LINE: [www.co.kittitas.wa.us/cds/request.asp](http://www.co.kittitas.wa.us/cds/request.asp) or 509-962-7694 •

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506