## **INSPECTION REPORT**

**PERMIT NUMBER:** 

BP-14-00821

OWNER'S NAME:

**MIFFLIN** 

DATE:	1/26/2015	TYPE:	Mono pour
TIME STARTED:	10:22 AM	INSPECTOR:	Amber Green
MAP NUMBER:	17-20-30051-0001		
	- d 1:		6 P
Ensure 5 setback is maintained at side property line.			
2. Set and secure hold-downs prior to pour.			
INSTRUCTIONS: Complete Above, then OK to POUR.			
NEXT INSPECTION: Floor Framing			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
amber.green @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			