## **INSPECTION REPORT**

PERMIT NUMBER:	BP-14-00823	OWNER'S NAME:	HANSON
DATE:	1/14/2015	TYPE:	Stove or fireplace
TIME STARTED:	9:29 AM	INSPECTOR:	Amber Green
MAP NUMBER:	18-18-21030-0007		
1. Cleara	nces ok		
2. Final o	k		
INSTRUCTIONS:			
NEXT INSPECTION:			
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:  amber.green @co.kittitas.wa.us			
• INSPEC	TION REQUEST LINE: www.co.kitti		

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506