## **INSPECTION REPORT**

PERMIT NUMBER:	BP-15-00094	OWNER'S NAME:	EATON
DATE:	4/24/2015	TYPE:	Radiant heat
TIME STARTED:	11:24 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-13050-0014		
1. hydror	nics at 100#-ok		
	sualtion ok		
INSTRUCTIONS: apply vapor barrier to insulation			
NEXT INSPECTION:	shearwalls		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQ	UIRED, RE-INSPECTION FEES MUST BE	PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUI	ESTIONS? PLEASE CONTACT THE INSPE		
jessica.contratto @co.kittitas.wa.us			
	<b>TION REQUEST LINE: <u>www.co.kitti</u> 1</b> N. Ruby Street, Suite 2, Ellensburg, V		