INSPECTION REPORT

PERMIT NUMBER:	BP-15-00120	OWNER'S NAME:	KITTITAS COUNTY HA
DATE:	9/20/2016	TYPE:	Mechanical and plumbir
TIME STARTED:	8:43 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	19-16-24051-0914		
 Mini split ok Exhaust ok DWV on stack-ok H20 at 75#-ok Install vapor barrier behind shower on exterior wall 			
INSTRUCTIONS:			
NEXT INSPECTION:	Framing		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			
INSPECTION REQUEST LINE: 509-962-7694			
http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx			
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			