



KITITITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

## INSPECTION REPORT

PERMIT NUMBER: BP-15-00208

OWNER'S NAME: FEASTER

DATE: 2/19/2016

TYPE: Re-inspection

TIME STARTED: 12:41 PM

INSPECTOR: Justin Bennett

MAP NUMBER: 20-14-24050-0112

1. Range hood Ok
2. Vanity electrical Ok
3. Fireplace not functional
4. Blower door not on site

**INSTRUCTIONS:** Email blower door & verify fireplace operation/Re-Inspection

**NEXT INSPECTION:** Re-Inspection

**RE-INSPECTION FEE DUE?**  NO  YES \$ \_\_\_\_\_

***IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION***

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  
ADDRESS: \_\_\_\_\_ [justin.bennett @co.kittitas.wa.us](mailto:justin.bennett@co.kittitas.wa.us)

**INSPECTION REQUEST LINE: 509-962-7694**

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506