KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-15-00238	**OWNER'S NAME:**	EVERGREEN VALLEY
DATE:	11/12/2015	**TYPE:**	Final
TIME STARTED:	12:40 PM	**INSPECTOR:**	Jessica Contratto
MAP NUMBER:	20-14-12053-0012		

	1. Complete condensate drain piping at air handler
	2. Energy credits met
	3. Blower door test ok
	4. Have WUIC performed by fire marshal
	5. Propane tank to be inspected by fire marshal
	6. Have access and septic approval signed off on permit card

INSTRUCTIONS: complete above, take pic of drain piping and email to address below. Fire marshal or CDS office personnel can sign CO when complete

NEXT INSPECTION: N/A

RE-INSPECTION FEE DUE? ☑ **NO** ☐ **YES** **$** _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

jessica.contratto **@co.kittitas.wa.us**