INSPECTION REPORT

PERMIT NUMBER: BP-15-00266 OWNER'S NAME: MANSON

DATE:	7/7/2015	TYPE:	Exterior shear	
TIME STARTED:	4:02 PM	INSPECTOR:	Justin Bennett	
MAP NUMBER:	18-17-01020-0005			
1. Drawin	gs not on site			
2. Drawin	gs must be on site to per	form an inspection		
3. Re-Insp	pection			
INSTRUCTIONS:				
NEXT INSPECTION	: Re-Inspection			
RE-INSPECTION FE	E DUE? NO	YES	\$	
IF RE	QUIRED, RE-INSPECTION FEE	S MUST BE PAID PRIOR TO SC	HEDULING A RE-INSPECTION	
C	QUESTIONS? PLEASE CONTACT	THE INSPECTOR AT THE FOLL		
		iustin.bennett @co	o.kittitas.wa.us	
		w.co.kittitas.wa.us/cds/red lensburg, WA 98926 • Main C	quest.asp or 509-962-7694 •	
	+11 IV. Nuby Street, Suite 2, El	iensburg, WA 30320 • Widili C	MINGE LINE. 303-302-7300	