INSPECTION REPORT

PERMIT NUMBER: BP-15-00282 OWNER'S NAME: BOITANO

DATE:	6/17/2015	TYPE:	Floor framing	
TIME STARTED:	8:50 AM	INSPECTOR:	Justin Bennett	
MAP NUMBER:	18-18-26051-0007			
1. Correc	tions Ok			
2. Floor Framing Ok				
3. Ok to o	over			
INSTRUCTIONS:	Ok to cover			
NEXT INSPECTION	: Shear Walls			
RE-INSPECTION FI	EE DUE? V NO	YES	\$	
IF RI	EQUIRED, RE-INSPECTION FEES N	IUST BE PAID PRIOR TO SC	HEDULING A RE-INSPECTION	
	QUESTIONS? PLEASE CONTACT TH			
		iustin.bennett @co	o.kittitas.wa.us	
	ECTION REQUEST LINE: <u>www.</u> 411 N. Ruby Street, Suite 2, Ellens			
	TIT IN. NUDY SUICEL, SUILE 2, EIIEIIS	Jours, WA JOJZU · WIdill C	7. THEC LINE. 303-302-7300	