INSPECTION REPORT

PERMIT NUMBER: BP-15-00292 OWNER'S NAME: STRADER

DATE:	7/16/2015	TYPE:	Footings
TIME STARTED:	2:31 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-19050-0145		
1. setbac	ks ok		
2. footing	s ok		
INSTRUCTIONS	ak ta naur aga interior nada	o ot wollo	
INSTRUCTIONS: ok to pour, see interior pads at walls			
NEXT INSPECTIO	N: walls		
RE-INSPECTION F	EE DUE?	YES NUST BE PAID PRIOR TO SC	\$ HEDULING A RE-INSPECTION
	QUESTIONS? PLEASE CONTACT TH	IE INSPECTOR AT THE FOLL	OWING E-MAIL ADDRESS:
		iessica.contratto @co	o.kittitas.wa.us
• INSI	PECTION REQUEST LINE: www. 411 N. Ruby Street, Suite 2, Ellen		
	411 N. Ruby Street, Suite 2, Ellen	spurg, WA 30320 • Wall C	JIIICE LIIIE. 303-302-7300