## **INSPECTION REPORT**

PERMIT NUMBER: BP-15-00299 OWNER'S NAME: PERAVOZ

DATE:	9/21/2015	TYPE:	Radiant heat
TIME STARTED:	10:32 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	21-14-34060-0003		
1. vapor barrier required or taped/sealed seams on insulation board			
INSTRUCTIONS: complete vapor barrier			
NEXT INSPECTION: re-inspect			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			