## **INSPECTION REPORT**

PERMIT NUMBER: BP-15-00329 OWNER'S NAME: LYNCH

DATE:	7/29/2015	TYPE:	Insulation
TIME STARTED:	3:26 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-17-15040-0002		
1. insulation needs to be face stapled to studs			
INSTRUCTIONS: complete above, ok to cover			
NEXT INSPECTION: final with fireplace installed			
RE-INSPECTION FEE	DUE? NO	YES	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 •			
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			