## **INSPECTION REPORT**

OWNER'S NAME: LYNCH

TYPE:

Final

PERMIT NUMBER: BP-15-00329

DATE:

8/21/2015

TIME S	STARTED:	2:01 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:		20-17-15040-0002		
	1. fireplace clearances/fresh air ok			
	2. final ok			
INSTRUCTIONS: final ok				
NEXT INSPECTION: N/A				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
iessica.contratto @co.kittitas.wa.us				
<ul> <li>INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 ◆</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506</li> </ul>				