INSPECTION REPORT

PERMIT NUMBER: BP-15-00338 OWNER'S NAME: KNOLL

DATE:		10/19/2015	TYPE:	Floor framing	
TIME STARTED:		11:39 AM	INSPECTOR:	Jessica Contratto	
		19-15-07059-0007			
	1. Gusset I	set both sides of post/beam connetion			
INSTRU	JCTIONS: O	k to cover			
NEXT I	NSPECTION:	shearwalls			
RE-INS	PECTION FEE	E DUE? NO	YES	\$	
	IF REC	QUIRED, RE-INSPECTION FEES	MUST BE PAID PRIOR TO SCH	HEDULING A RE-INSPECTION	
	QI	JESTIONS? PLEASE CONTACT	THE INSPECTOR AT THE FOLLO	OWING E-MAIL ADDRESS:	
			iessica.contratto @co	.kittitas.wa.us	
		CTION REQUEST LINE: <u>wwv</u> 11 N. Ruby Street, Suite 2, Elle		uest.asp or 509-962-7694 ◆ ffice Line: 509-962-7506	