



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-15-00365 OWNER'S NAME: FORTUNE CREEK
DATE: 11/30/2015 TYPE: Mechanical and plumbir
TIME STARTED: 9:40 AM INSPECTOR: Jessica Contratto
MAP NUMBER: 19-15-07061-0028

	1. Furnace ductwork ok
	2. Exhaust ductwork ok
	3. Shorten exhaust fan run from basement bath where buched up at termination
	4. Gas not at minimum of 15# for test
	5. **Note: Spray foam insulation or spray foam/batt combo must be used in unvented rafters

INSTRUCTIONS: ok to call for framing. Have gas on test. Address exhaust duct by insulation

NEXT INSPECTION: framing

RE-INSPECTION FEE DUE? NO YES \$ _____
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

• **INSPECTION REQUEST LINE:** www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506