INSPECTION REPORT

PERMIT NUMBER:	BP-15-00379	OWNER'S NAME:	YUCKERT
DATE:	10/20/2016	TYPE:	Final
TIME STARTED:	1:17 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	17-16-14040-0002		
 Caulk exterior penetration @ gas line Complete/make safe exterior electrical @ rear double doors Water not on to verify Plumbing Final Gas Range not operational Range Hood not installed Fireplace not operational Fan required in Master WIC for Stacked Washer/Dryer? Master shower has exhaust fan installed inside enclosure? Furnace and Coil require P-traps INSTRUCTIONS: Complete above/Re-Inspection			
NEXT INSPECTION:	Re-Inspection		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
	QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: justin.bennett @co.kittitas.wa.us		
ADDITION			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506