INSPECTION REPORT

PERM	IT NUMBER:	BP-15-00409	OWNER'S NAME:	VOSHALL/OWENS	
DATE:		9/22/2015	TYPE:	Final	
TIME STARTED:		10:59 AM	INSPECTOR:	Jessica Contratto	
MAP	NUMBER:	18-18-22054-0004			
	Complete sealing of building exterior (caulk around window, door trim and siding seams)				
	2. complete electrical cover on exterior				
	3. Blower door test cannot exceed 5 ACH. Currently 5.6				
	4. Adjust hinges on door to garage to be self closing				
	5. WUIC ok				
	6. Platforms at bedroom windows ok				
INSTRUCTIONS: complete above, call for re-inspection					
NEXT INSPECTION: re-inspection					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	<u>iessica.contratto</u> @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 					