## **INSPECTION REPORT**

OWNER'S NAME: SCHULER

PERMIT NUMBER: BP-15-00412

DATE:		8/13/2015	TYPE:	Exterior shear	
TIME STARTED:		11:23 AM	INSPECTOR:	Justin Bennett	
MAP NUMBER:		20-14-12053-0013			
	1. HD's Ok				
	2. Exterior S	. Exterior Shear Ok			
	3. Verify garage 2W4's @ interior shear				
	4. Ok to cover exterior				
INSTRUCTIONS: Ok to cover exterior					
NEXT INSPECTION: Plumb/Mech					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	<u>iustin.bennett</u> @co.kittitas.wa.us				
<ul> <li>INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926</li> <li>Main Office Line: 509-962-7506</li> </ul>					
, , , , , , , , , , , , , , , , , , , ,					