



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-15-00636

OWNER'S NAME: CARTER

DATE: 6/1/2016

TYPE: Final

TIME STARTED: 10:25 AM

INSPECTOR: Jessica Contratto

MAP NUMBER: 17-20-29054-0004

1. Complete tank placement inspection and hook up gas for appliances
2. Seal around duct in garage
3. Sewer ok
4. Obtain access approval from public works
5. Blower door test results not on site
6. Heat pump is 1 energy credit. .5 still needed. Contractor is trying for 4.0 ACH on blower door

INSTRUCTIONS: complete above, re-inspect

NEXT INSPECTION: re-inspect

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: _____ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506