INSPECTION REPORT

MOI ECHOIT KEI OKI			
PERMIT NUMBER:	BP-15-00700	OWNER'S NAME:	BOLSTAD
DATE:	11/2/2016	TYPE:	Final
TIME STARTED:	12:37 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-20058-0076		
 Provide sewer connection letter Garage separation door to be self closing Main floor master and guest master bedrooms need smoke/CO detectors outside of room. Verify low volt detector outside guest bed is a combo unit Plumbing ok Blower door ok Energy credits ok All other requirements for final have been met INSTRUCTIONS: Complete first 3 above corrections, re-inspection			
NEXT INSPECTION:	Re-inspection		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: iessica.contratto @co.kittitas.wa.us			
ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506