INSPECTION REPORT

PERMIT NUMBER:	BP-15-00761	OWNER'S NAME:	CATLIN
DATE:	5/17/2016	TYPE:	Shearwalls
TIME STARTED:	12:06 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-19-06090-0007		
1. Gypsum shea 2. Other interior 3. Gas at 19#-ok 4. Master showe	(
INSTRUCTIONS: Complete screw pattern on gypsum wall both sides. Call for re-inspection			
NEXT INSPECTION: Re-inspection			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506