INSPECTION REPORT

PERMIT NUMBER:	BP-15-00798	OWNER'S NAME:	ZIEGLER
DATE:	4/11/2016	TYPE:	Exterior shear
TIME STARTED:	12:06 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-15-29051-0094		
2. HD's must be	p on south side (clouded on dwg- installed on 2 full height studs (2 installation on North wall	•	
INSTRUCTIONS: Complete corrections above/Once complete Ok to cover exterior/Provide engineer approval or revise HD installation NEXT INSPECTION: Plumb/Moch			
NEXT INSPECTION:	Plumb/Mech		
RE-INSPECTION FEE	DUE? NO YES	PAID PRIOR TO SCHE	\$ DULING A RE-INSPECTION
	QUESTIONS? PLEASE CONTACT THE I	NSPECTOR AT THE FO iustin.bennett @	

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506